


CHEF

CH 179..

CH 180..

CH 185..


CH 985..



IST093
Rev.2017.05

1


Montaggio Assembly



$65 \pm 5^{\circ}\text{C}$



$15 \pm 5^{\circ}\text{C}$




MIN - MAX






OK

2 a


180 179




b



C




180 179



985 185

CH11


180 179




$\varnothing 33,5$

985 185

285 985





$\varnothing 35$





360°

Funzionamento
Working




179

185 285




985

185









179

180



M

Manutenzione
Service




S


Sostituzione Cartuccia
How to replace Cartridge

180 179 985 185


a




Sostituzione Flex e Doccetta
How to replace Flex and Hand Shower




185 179 985



Sostituzione Aeratore
How to replace Aerator




180



d

185
985



e

Sostituzione Raccordo Canna
How to replace Connection for Spout

180
179

